

LABOR AND MATERIALS

1	Copper Lead	{ Connection $\frac{3}{4}$ "	\$ 2.29
1	Curb	{ Cock Valve T.S. & V. } $\frac{3}{4}$ in.	\$ 2.70
1	Service box Old returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff or Rdway	\$ 4.25
8	Ft. $\frac{3}{4}$ in.	{ Copper G.I. C.I. } Pipe at	\$ 2.80
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Inc'g	{ Coupl'gs to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Lead Joints at		\$ 11.25
	Compound Joints at		\$
	Hrs. Water Maint. Man—1 at		\$
3	Hrs. Water Maint. Man—2 at		\$ 3.06
9	Hrs. Labor—	at 91	\$ 8.19
	Hrs. Labor—	at	\$
	Hrs. Compressor at		\$
	Compensation Ins. at \$	per C.	\$ 25
	Trucking		\$ 1-
	Pav't Patch	B.P.	\$
	O'head		\$
			\$ 24.54

124-1750

Before Paving

Grand

St. Pt. Ave. No. 27-29

Name of Owner
Robert Cronin

Labor and Mat'l. Report July 5 1950

#29 #27

25'2" 25'6"

● Curb Box

4" Main

Elev. of Main at tap 5'

Gate at ● ● Gate at

TAX ID # 302.16-21-13

● Curb Box