

LABOR AND MATERIALS

1	Copper Lead	{ Connection	3/4"		\$ 2.29
1	Curb	{ Cock Valve T. S. & V. }	3/4" in.		\$ 2.70
	Service box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway }			\$ 4.25
260	Ft.	{ Copper G. I. C. I. }	3/4 in.	Pipe at 35	\$ 9.10
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	{ Coupl'gs	to in. at		\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints at				\$
	Compound Joints at				\$
	Hrs. Water Maint. Man-1 at				\$
	Hrs. Water Maint. Man-2 at				\$ 1.02
5	Hrs. Labor	at	91		\$ 45.5
	Hrs. Labor	at			\$
	Hrs. Compressor at				\$
	Compensation Ins. at \$	per C.			\$ 1.12
	Trucking				\$ 1.-
	Pav't Patch	B. P.			\$
					\$
					\$
					\$
	O'head				\$
					\$ 25.03

Before Taping

101-1930

St. ~~PH~~
Ave. No. 6

Grand

Name of Owner
Gates (Comm of Public Welfare)

Labor and Mat'l. Report July 5 1950

#6

16'8"

26'9"

● Curb Box

4" Main

Elev. of Main at tap 5

● Gate at

● Gate at

● Curb Box

LSM-5C 10-21-49