

### LABOR AND MATERIALS

1 Copper } Connection 3/4 \$ \_\_\_\_\_  
 1 Curb } Cock } 3/4 in. \$ \_\_\_\_\_  
           } Valve }  
           } T.S. & V. }  
 1 Service box { Short 3-1/2 x 4-1/2 } \$ \_\_\_\_\_  
   Old returned { Long 4-1/2 x 5-1/2 }  
 24 Ft. 3/4 in. { Copper } Pipe at \$ \_\_\_\_\_  
                           { Galv. }  
                           { Cl. }  
 \_\_\_\_\_ Nipples \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 \_\_\_\_\_ Bushings \_\_\_\_\_ to \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 \_\_\_\_\_ Red'g \_\_\_\_\_  
 \_\_\_\_\_ Inc'g \_\_\_\_\_  
 \_\_\_\_\_ Union \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 \_\_\_\_\_ Meter \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ Compound Joints at \$ \_\_\_\_\_  
 \_\_\_\_\_ Maintenance Foreman \$ \_\_\_\_\_  
 \_\_\_\_\_ Hrs. Water Maint. Man - 1 at \$ \_\_\_\_\_  
 \_\_\_\_\_ Hrs. Water Maint. Man - 2 at \$ \_\_\_\_\_  
 \_\_\_\_\_ Hrs. Garage Foreman \_\_\_\_\_ at \$ \_\_\_\_\_  
 \_\_\_\_\_ Hrs. Labor \_\_\_\_\_ at \$ \_\_\_\_\_  
 \_\_\_\_\_ Hrs. Compressor at \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ Trucking \$ \_\_\_\_\_  
 \_\_\_\_\_ Pav't Patch \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_

GRAND St. Ave. No. 36-38  
 Name of Owner C. Fox  
 Labor and Mat'l. Report 1938, APR. 26



25'-6" 34'

● Curb Box

4" Main (GALV.) Elev. of Main at tap 5'  
 Gate at ● Gate at

TAX ID # 302.16-17-49

● Curb Box

OLD TAP DISCONNECTED