

LABOR AND MATERIALS

1	Copper	Connection	3/4"	\$	2.29
	Lead				
1	Curb	Cock Valve T.S. & V.	3/4" in.	\$	2.70
1	Service box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$	4.25
8	Ft.	Copper G.I. C.I.	3/4 in. Pipe at	35 \$	2.80
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Coupl'gs	to in. at	\$	
	Union	in. at		\$	
	Meter	in. at		\$.90
	Lead Joints at			\$.20
	Compound Joints at			\$	
	Hrs. Water Maint. Man-1 at			\$	
8	Hrs. Water Maint. Man-2 at		1.02	\$	8.16
14	Hrs. Labor—	at	91	\$	12.74
	Hrs. Labor—	at		\$	
	Hrs. Compressor at			\$	
	Compensation Ins. at \$	per C.		\$.49
	Trucking			\$	1.00
	Pav't Patch		B.P.	\$	
	O'head			\$	
				\$	34.41

117. 1150

Before Paving

Grand

St. Pr. Ave. No. 11

Name of Owner

O'Neil Bros.

Labor and Mat'l. Report

July 5 19 50

● Curb Box

● Curb Box