

LABOR AND MATERIALS

1	Copper Lead	} Connection	3/4"	_____	\$ _____
1	Curb Cock Valve J.S. & V.				
1	Service box Old returned	{	Short 3-1/2 x 4-1/2 Long 4-1/2 x 5-1/2	_____	\$ _____
25	Ft. 3/4" in.				
_____	Nipples _____	in. at _____	\$ _____		
_____	Bushings _____	to _____	in. at _____	\$ _____	
_____	Red'g _____				\$ _____
_____	Inc'g _____				\$ _____
_____	Union _____	in. at _____			\$ _____
_____	Meter _____	in. at _____			\$ _____
_____					\$ _____
_____	Compound Joints at _____				\$ _____
_____	Maintenance Foreman _____				\$ _____
_____	Hrs. Water Maint. Man - 1 at _____				\$ _____
_____	Hrs. Water Maint. Man - 2 at _____				\$ _____
_____	Hrs. Garage Foreman _____	at _____			\$ _____
_____	Hrs. Labor _____	at _____			\$ _____
_____	Hrs. Compressor at _____				\$ _____
_____					\$ _____
_____	Trucking _____				\$ _____
_____	Pav't Patch _____				\$ _____
_____					\$ _____
_____					\$ _____
_____					\$ _____
_____					\$ _____
_____					\$ _____

GRANT Ave. No. 16

Name of Owner TAX ID # 302.20-1-10

Labor and Mat'l. Report 1934, NOV. 19



21'11" 35'11"

● Curb Box

4" Main Elev. of Main at tap 4 1/2

Gate at ● Gate at ●

● Curb Box

OLD TAP SHUT OFF AT MAIN