

**Labor and Materials**

	Copper } Connection	?	\$ 2.60
1	Lead } Connection	1	
1	Curb } Cock Valve	3	\$ 2.27
	} V.		
1	Service Box } <del>Short 4 1/2 x 5 1/2</del>		\$ 1.59
	} Long 4 1/2 x 5 1/2		
	} <del>Sum of above</del>		
24	Ft. in. } Copper Pipe at	3	\$ 4.32
	} Galv. Iron		
	} Cast Iron		
	Nipples in. at	4	\$
	Bushings to in. at		\$
	Red'g } Couplings to in. at		\$
	Inc'g }		
	Union in. at		\$
	Meter in. at		\$
	Lbs. Br. Stone at		\$
	Lbs. Sand at		\$
	Bags Cement at		\$
	Paving Brick } Mack		\$
	} Red		
	} Asphalt		
	Lead Joints at		\$
	Leadite Joints at		\$
10.0	Hrs. Foreman at	1.88	\$ 1.88
	Hrs. Common Labor at	3.60	\$ 3.60
	Hrs. Common Labor at		\$
	Hrs. Mason at		\$
	Hrs. Mason's Helper at		\$
	Hrs. Compressor at		\$
	Compensation Ins		\$ .17
	Trucking	1.17	\$ 1.17
	Builders' Use of Water		\$
	<b>Total</b>	<b>17.43</b>	<b>\$ 17.43</b>

**Labor and Material Report**

August 6 1938

61 Great Lakes -  
 No measurement  
 New house  
 Mrs. Shurtz

● Curb Box

6 Main

Elev of Main at tap 5

Gate at ●

● Gate at

● Curb Box