

LABOR AND MATERIALS

1	Copper } Connection	3/4	\$	
	Lead }			
1	Curb } Cock	1" in.	\$	
	Valve }			
	T.C. & V. }			
1	Service box { Short 3-1/2 x 4-1/2		\$	
	Old returned { Long 4-1/2 x 5-1/2			
10 1/2	Ft. 1" in. { Copper } Pipe at		\$	
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g			
	Inc'g			
	Union	in. at	\$	
	Meter	in. at	\$	
			\$	
	Compound Joints at		\$	
	Maintenance Foreman		\$	
	Hrs. Water Maint. Man - 1 at		\$	
	Hrs. Water Maint. Man - 2 at		\$	
	Hrs. Garage Foreman	at	\$	
	Hrs. Labor	at	\$	
	Hrs. Compressor at		\$	
			\$	
	Trucking		\$	
	Pav't Patch		\$	
			\$	
			\$	
			\$	
			\$	

GRANT

Ave. No. 74

Name of Owner

Labor and Mat'l. Report 19 24, DEC. 8



39-4 32-10

● Curb Box

6" Main

Elev. of Main at tap 4 1/2'

Gate at ●

● Gate at

● Curb Box