

LABOR AND MATERIALS

1	Copper } Connection	3/4"	\$
1	Curb } Cock } Valve } F.C. & V. }	3/4" in.	\$
1	Service box } Old returned }	Short 3-1/2 x 4-1/2 Long 4-1/2 x 5-1/2	\$
25	Ft. 3/4 in. } Copper } Gal. } Gal. }	Pipe at	\$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g		
	Inc'g		
	Union	in. at	\$
	Meter	in. at	\$
			\$
	Compound Joints at		\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man - 1 at		\$
	Hrs. Water Maint. Man - 2 at		\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor at		\$
			\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$

LOT TAP

GRANT

Ave. No. 75

Name of Owner

Labor and Mat'l. Report 19 35, OCT. 21



47'9" 53'11"

● Curb Box

6" Main

Elev. of Main at tap 4'

Gate at ●

● Gate at

● Curb Box

MEASURED FROM #73

LOT TAP