

## LABOR AND MATERIALS

Copper	{	Connection	-----	\$			
Lead							
Curb	{	Cock Valve	----- in.	\$			
		T. S. & V.					
Service Box	{	Short 3 1/2 x 4 1/2	} -----	\$			
Old returned		Long 4 1/2 x 5 1/2					
		Buff. or Rdway					
Ft. -----		in.					
		{	Copper	} Pipe at -----			
			Galv Iron				
			Cast Iron				
Nipples	-----	in.	at -----	\$			
Bushings	-----	to -----	in.	at -----	\$		
Red'g	{	Couplings	-----	to -----	in.	at -----	\$
Inc'g							
Union	-----	in.	at -----	\$			
Meter	-----	in.	at -----	\$			
Lead Joints	-----	at -----		\$			
Leadite Joints	-----	at -----		\$			
Hrs. Foreman	-----	at -----		\$			
Hrs. Chauffeur	-----	at -----		\$			
Hrs. Tapper	-----	at -----		\$			
Hrs. Labor	-----	at -----		\$			
Hrs. Labor	-----	at -----		\$			
Hrs. Compressor	-----	at -----		\$			
Compensation Ins.	-----			\$			
Trucking	-----			\$			
Builders Use of Water	-----			\$			
	-----			\$			
	-----			\$			
	-----			\$			
	-----			\$			

St. \_\_\_\_\_  
 Pt. \_\_\_\_\_  
 Ave. No. 87

*Grant*

Name of Owner \_\_\_\_\_

---

*Sept - 1928 - office*

Labor and Mat'l. Report Aug 22 1929

---

----- Main -----

Gate at ●

Elev. of Main at tap -----

● Gate at

---

● Curb Box