

LABOR AND MATERIALS

1	Copper Lead	{ Connection	3/4		\$
1	Curb	{ Cock Valve T. S. & W.	3/4	in.	\$
1	Service Box	}	Short 2 1/2 x 4 1/2		\$
	Old returned		Long 4 1/2 x 5 1/2		
28	28 Ft.		3/4	in.	
		{ Copper Galv. Iron Cast Iron		Pipe at	\$
	Nipples			in. at	\$
	Bushings			to in. at	\$
	Red'g Inc'g	{ Couplings		to in. at	\$
	Union			in. at	\$
	Meter			in. at	\$
	Lead Joints			at	\$
	Leadite Joints			at	\$
	Hrs. Foreman			at	\$
	Hrs. Chauffeur			at	\$
	Hrs. Tapper			at	\$
	Hrs. Labor			at	\$
	Hrs. Labor			at	\$
	Hrs. Compressor			at	\$
	Compensation Ins.				\$
	Trucking				\$
	Builders Use of Water				\$
					\$
					\$
					\$
					\$
					\$
					\$

Grant

101

Ave. No. 99

Name of Owner

Labor and Mat'l. Report

Oct. 25 1935



6" Main

Elev. of Main at tap 4 1/2'

Gate at ●

● Gate at

● Curb Box

VACANT LOT