

LABOR AND MATERIALS

1	Copper } Connection	3/4	\$	
1	Curb } Cock Valve } T.S. & V. }	3/4 in.	\$	
1	Service box } Short 3-1/2 x 4-1/2 } Old returned } Long 4-1/2 x 5-1/2 }		\$	
25	Ft. 3/4 in. } Copper }		\$	
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g			
	Inc'g			
	Union	in. at	\$	
	Meter	in. at	\$	
			\$	
	Compound Joints at		\$	
	Maintenance Foreman		\$	
	Hrs. Water Maint. Man - 1 at		\$	
	Hrs. Water Maint. Man - 2 at		\$	
	Hrs. Garage Foreman	at	\$	
	Hrs. Labor	at	\$	
	Hrs. Compressor at		\$	
			\$	
	Trucking		\$	
	Pav't Patch		\$	
			\$	
			\$	
			\$	
			\$	
			\$	

St. No. 7
GRAVES
 Name of Owner _____
 Labor and Mat'l. Report 19 26, MAY 27



39' 37'

● Curb Box

6" Main Elev. of Main at tap 4'
 Gate at ● ● Gate at

● Curb Box

NEW HOUSE