

### LABOR AND MATERIALS

1	Copper Lead	} Connection	<u>3/4</u>		\$ 1.79
1	Curb	Clock Valve F. S. & V.	<u>3/4</u>	in.	\$ 2.61
1	Service box Old returned	Short 3/4 X 4 1/2 Long 4 1/2 X 5 1/2 Buff for Rdway			\$ 1.82
<u>25</u>	<u>3/4</u>	in.	} Copper Galv. Iron Cast Iron	} Pipe at <u>23</u>	\$ <u>5.75</u>
.....Nipples.....in. at.....\$					
.....Bushings.....to.....in. at.....\$					
.....Red'g Inc'g } Couplings.....to.....in. at.....\$					
.....Union.....in. at.....\$					
.....Meter.....in. at.....\$					
.....Lead Joints at.....\$					
.....Compound Joints at.....\$					
1	Hrs. Foreman at	WWM	<u>9 1/2</u>	\$ <u>93</u>	
2	Hrs. Chauffeur at		<u>8 1/2</u>	\$ <u>165</u>	21
6	Hrs. Tapper at	St. K. Mech.	<u>9 1/2</u>	\$ <u>5.77</u>	21
4	Hrs. Labor at		<u>7 1/2</u>	\$ <u>2.86</u>	
.....Hrs. Labor at.....\$					
.....Hrs. Compressor at.....\$					
.....Compensation Ins.....\$ <u>31</u>					
.....Trucking.....\$ <u>1.00</u>					
.....Builders Use of Water.....\$ <u>9.00</u>					
..... <u>Truly &amp; Carroll</u> .....\$					
.....\$					
.....\$					
.....\$					
\$ <u>33.49</u>					

St. Grove Ave  
 Pl. Ave. No. 10

Name of Owner Rose

---

Labor and Mat'l. Report Aug 23 1946

6" Main

Gate at ●

Elev. of Main at tap 5'

● Gate at

● Curb Box

LSM-5C-6-1-45