

**Labor and Materials**

1	Copper	} Connection. 3/4"	.....	\$. 1.33
1	Lead			
1	Curb	} Cock Valve T.S.&V. } 3/4" in	.....	\$. 1.58
1	Service Box			
	Old returned	} Short 3 1/2 x 4 1/2 } Long 4 1/2 x 5 1/2 } Buff or Rdwar }	.....	\$. 1.36
9	Ft. 3/4 in.			
		} Copper Galv. Iron Cast Iron } Pipe at	.....	\$. .86
	Nipples			
	Bushings	..... to ..... in. at	.....	.....
	Red'g Inc'g	} Couplings..... to ..... in. at	.....	.....
	Union.....			
	Meter.....	..... in. at	.....	.....
	Lbs. Br. Stone	at	.....	.....
	Lbs. Sand	at	.....	.....
	Bags Cement	at	.....	.....
	Paving Brick	} Mack Red Asphalt } at	.....	.....
	Lead Joints			
	Leadite Joints	at	.....	.....
4	Hrs. Foreman	at	.....	\$. 2.50
	Hrs. Common Labor	at	.....	.....
	Hrs. Common Labor	at	.....	.....
	Hrs. Mason	at	.....	.....
	Hrs. Masons Helper	at	.....	.....
	Hrs. Compressor	at	.....	.....
	Compensation Ins	.....	.....	\$. 1.08
	Trucking	.....	.....	.....
	Builders Use of Water	.....	.....	.....
Total \$.				8.71

32-81 made hole in pt.  
 Labor and Material Report Oct 27 1923

3/4" tap at 45 Grove Ave.



6 Main Elev. of Main at tap 4 ft  
 Gate at ● Gate at ●

● Curb Box  
 Old tap shut off

OK OK