Labor and Materials

1	Lead Connection 3/4	$
1	Curb Cock 1	$
	Service Box Old returned { Short 3½ x 4½ / ~~Long 4½ x 5½~~ / Buffalo	$
8	Ft. 1 in. G. I. Pipe at	$
	Nipples in. at	$
1	Bushings 4" to 3/4 in. at	$
	Red'g Coup to in. at	$
	Inc'g Coup to in. at	$
	Union in. at	$
	Meter in. at	$
	Cu. Yds. Br. Stone at	$
	Cu. Yds. Sand at	$
	Bags Cement at	$
	Paving Brick { Mack / Red / Asphalt } at	$
2	Hrs. Foreman at	$
8	Hrs. Common Labor at	$
	Hrs. Mason at	$
	Hrs. at	$
	Hrs. at	$
No	Builders' Use of Water	$
	at	$
	at	$
	at	$
Pavment	at	$
	Total	$

Labor and Material Report 9 May 1924

49 Grove Av. (Old com)

6" Main

Elev. of Main at tap 4½

Gate at ●

● Gate at

● Curb Box

Pavment
½ Pavment Tap 1 to 48