

LABOR AND MATERIALS

1	Copper	} Connection	3/4"	\$		
1	Lead					
1	Curb	} Cock	3/4" in.	\$		
					} Valve	
		} T.S. & V.				
1	Service box		{		\$	
Old returned		Short 3 1/2 x 4 1/2				
		Long 4 1/2 x 5 1/2				
29	Ft. 3/4 in.	{		\$		
					Copper	
					G.I. / C.I.	
	Nipples	in.	at	\$		
	Bushings	to	in.	at	\$	
	Red'g } Inc'g }	Coupl'gs	to	in.	at	\$
	Meter	in.	at	\$		
	Lead Joints				\$	
	Compound Joints				\$	
	Maintenance Foreman				\$	
	Hrs. Water Maint. Man-1	at			\$	
	Hrs. Water Maint. Man-2	at			\$	
	Hrs. Garage Foreman	at			\$	
	Hrs. Labor	at			\$	
	Hrs. Compressor	at			\$	
	Compensation Ins.	\$	per C	\$		
	Trucking				\$	
	Pav't Patch				\$	
Tap by Gigcord F					\$	
Cb. 5-18-59					\$	
	O'head				\$	
					\$	

V

Grove

St.
 Pt.
 Ave. No. 59

Name of Owner Anthony Jones

Labor and Mat'l. Report May 18 19 59

40'

34' 3"

6" Main

Elev. of Main at tap 5 1/2'

Gate at •

• Gate at

• Curb Box

LSM-SC-2-5 56