

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4"		\$
1	Curb	Cock Valve	3/4 in.		\$
		T.S. & V.			\$
1	Service box	Short 3 1/2 x 4 1/2			\$
	Old returned	Long 4 1/2 x 5 1/2			\$
		Buff or Rdway			\$
39	Ft. 3/4 in.	Copper		Pipe at	\$
		G.I.			\$
		C.I.			\$
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g				\$
	Inc'g	Coupl'gs. to in. at			\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints at				\$
	Compound Joints at				\$
	Maintenance Foreman				\$
	Hrs. Water Maint. Man-1 at				\$
	Hrs. Water Maint. Man-2 at				\$
	Hrs. Garage Foreman at				\$
	Hrs. Labor at				\$
	Hrs. Compressor at				\$
	Compensation Ins. at \$			per C	\$
	Trucking				\$
	Pav't Patch				\$
	Tap by G. S. GORDON				\$
	Co. 8-31-60				\$
	O'head				\$
					\$

-St.
Pl.
Ave. No. 17

Halsey

Name of Owner
Velma Y. Strasser

Labor and Mat'l. Report Aug. 31 1960

