

### Labor and Materials

1	Copper Lead	Connection	3/4	\$ 3.20
1	Curb	{ Cock Valve T-S. & V. }	3/4 in.	\$ 1.00
1	Service Box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway }		\$ 1.30
19	Ft.	{ Copper Galv. Iron Cast Iron }	3/4 in. Pipe at	\$ 4.18
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	{ Mack Red Asphalt }	at	\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
2	Hrs. Foreman	at	6.25	\$ 1.25
	Hrs. Common Labor	at		\$
	Hrs. Common Labor	at		\$
24	Hrs. Mason	at	Labor 50	\$ 12.00
	Hrs. Mason's Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$ 3.50
	Trucking			\$ 1.00
	Builders' Use of Water			\$
Total				\$ 24.28

26-45

22

### Labor and Material Report

June 4, 1926

12. Harlem St.



22

4" Main

Elev. of Main at tap 6'

Gate at ●

● Gate at

● Curb Box