

Labor and Materials

1.	Copper Lead	} Connection $\frac{3}{4}$			\$ 1.43
1.	Curb	} Cuck Valve T-S. & V.	} $\frac{3}{4}$ in		\$ 1.88
1.	Service Box Old returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff. or Rdway	}		\$ 1.75
27 Ft.	$\frac{3}{4}$ in.	{ Copper Galv-Iron Cast-Iron	} Pipe at 16		\$ 486
.....	Nipples	\$
.....	Bushings	\$
.....	Red'g Inc'g	{ Couplings.....	\$
.....	Union	\$
.....	Meter	\$
.....	Lead Joints	\$
.....	Leadite Joints	\$
.....	Hrs. Foreman	\$
3	Hrs. Chauffeur	\$ 1.88
4	Hrs. Tapper	\$ 2.50
4	Hrs. Labor	\$ 1.80
.....	Hrs. Labor	\$
4	Hrs. Compressor	\$ 3.50
.....	Compensation Inv.	\$ 19
.....	Trucking	\$ 1.00
.....	Builders Use of Water	\$ 2.50
.....	\$
.....	\$
.....	\$
					\$ 23.29

Lump Sum

8 - 1938

St. _____
Pt. _____
Ave. No. 16

Name of Owner
Mason

Labor and Mat'l. Report May 28 1938

44'7" 37'6"
● Curb Box

4 Main Elev. of Main at tap 5

Gate at ● ● Gate at

● Curb Box

Paid New House