

Labor and Materials

1	Copper	Connection	3/4"	\$	96
1	Lead			\$	
1	Curb	Cock Valve T.C.&V.	3/4" in	\$	1.33
1	Service Box	Short 3 1/2 x 4 1/2		\$	1.35
	Old returned	Long 4 1/2 x 5 1/2		\$	
		Buff. or Rdwe.		\$	
26	Ft.	3/4" in.	Copper Galv. Iron Cast Iron	Pipe at 1 1/2"	\$ 3.90
	Nipples in. at		\$	
	Bushings to in. at		\$	
	Red'g Inc'g	Couplings to in. at	\$	
	Union in. at		\$	
	Meter in. at		\$	
	Lbs. Br. Stone	at		\$	
	Lbs. Sand	at		\$	
	Bags Cement	at		\$	
	Paving Brick	Mack Red Asphalt	at	\$	
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
	Hrs. Foreman	at		\$	
	Hrs. Common Labor	at		\$	
	Hrs. Common Labor	at		\$	
	Hrs. Mason	at		\$	
	Hrs. Masons Helper	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins			\$	
	Trucking			\$	
	Builders Use of Water	1 1/2 patch		\$	
	Total			\$	

119

Labor and Material Report *Nov 23* 19*46*

26 Harrison Ave 3/4" tap



4" Main Elev. of Main at tap 0"

Gate at ● TAX ID # 302.19-20-4 ● Gate at

Old tap shut off ● Curb Box

[Handwritten signature]