

### Labor and Materials

1	Copper } Connection.....	3	320
1	Curb } Cock Valve } T. S. & V. } 3 in.....	3	180
1	Service Box } <del>Short 2 1/2</del> } Long 4 1/2 x 5 1/2 } Old returned } Buff. or Rdway }.....		140
8	Ft. .... in. } Copper } Galv. Iron } Cast Iron } Pipe at.....		176
	Nipples..... in. at.....		\$
1	Bushings. 3/4 to 1/2 in. at.....		07
	Red'g } Inc'g } Couplings..... to..... in. at.....		\$
	Union..... in. at.....		\$
	Meter..... in. at.....		\$
	Lbs. Br. Stone at.....		\$
	Lbs. Sand at.....		\$
	Bags Cement at.....		\$
	Paving Brick } Mack } Red } Asphalt } at.....		\$
	Lead Joints at.....		\$
	Leadite Joints at.....		\$
7	Hrs. Foreman at.....	62.5	250
	Hrs. Common Labor at.....		\$
11	Hrs. Common Labor at.....	70 3/8	446
	Hrs. Mason at.....		\$
	Hrs. Mason's Helper at.....		\$
	Hrs. Compressor at.....		\$
	Compensation Ins.....		15
	Trucking.....		1.00
	Builders' Use of Water.....		\$
Total			1559

27-64

Labor and Material Report

19

3



4 Main

Elev. of Main at tap 4 1/2

Gate at ●

● Gate at

● Curb Box

Old lead shut off