

Labor and Materials

1	Copper } Connection	3/4	\$ 320
	Lead } Cock	3/4	
	Curb } Valve	3/4 in.	\$ 100
		3/4	
	Service Box } Short 3 1/2 x 4 1/2		
	Old returned } Long 4 1/2 x 5 1/2		\$ 140
		Buff. or Rdway	
13	Ft. 3/4 in. } Copper		
		Galv. Iron } Pipe at	286
		Cast Iron	
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g } Couplings	to in. at	\$
	Inc'g }		
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone at		\$
	Lbs. Sand at		\$
	Bags Cement at		\$
	Paving Brick } (Mack		
		Red } at	\$
		Asphalt }	
	Lead Joints at		\$
	Leadite Joints at		\$
	Hrs. Foreman at		\$
	Hrs. Common Labor at		\$
	Hrs. Common Labor at		\$
	Hrs. Mason at		\$
	Hrs. Mason's Helper at		\$
	Hrs. Compressor at		\$
	Compensation Ins.		\$
	Trucking		\$ 100
	Builders' Use of Water		\$
	Total \$		

Labor and Material Report

June 11 1927

40 Harrison Ave
 [unclear] [unclear]



Crandall St. ● Curb Box

10"

Main

Elev. of Main at tap

41'

Gate at ●

● Gate at

● Curb Box

old tap
 shut off