

**Labor and Materials**

Copper } Connection.....	3	\$260
Lead } .....	4	
Curb } Cock Valve } .....	3 in.	\$224
} T.S. & V. } .....		
Service Box } Short 3 3/4 x 1 1/2 } .....		\$154
Old returned } Long 4 1/2 x 5 1/2 } .....		
} Bull or Redway } .....		
18 Ft. 3/4 in. } Copper } Pipe at.....		\$224
} <del>Cast Iron</del> } .....		
} <del>Cast Iron</del> } .....		
Nipples.....	in. at.....	\$
Bushings.....	to..... in. at.....	\$
Red'g } Couplings.....	to..... in. at.....	\$
Inc'g } .....		
Union.....	in. at.....	\$
Meter.....	in. at.....	\$
Lbs. Br. Stone at.....		\$
Lbs. Sand at.....		\$
Bags Cement at.....		\$
Paving Brick } Mack } at.....		\$
} Red } .....		
} Asphalt } .....		
Lead Joints at.....		\$
Leadite Joints at.....		\$
8 1/2 Hrs. Foreman at.....		\$5.31
6 Hrs. Common Labor at.....	45	\$2.70
Hrs. Common Labor at.....		\$
Hrs. Mason at.....		\$
Hrs. Mason's Helper at.....		\$
3 1/2 Hrs. Compressor at.....	8 1/2	\$3.06
Compensation Ins.....		25
Trucking.....		1-
Builders' Use of Water Patch (Sewer).....		\$2.50
Total \$		24.51

32-9  
 Labor and Material Report *Mar 18 1932*  
 42 Harrison Ave

4 Main Elev of Main at tap *5*

Gate at ● ● Gate at

● Curb Box

*New House*

*C.R. 4/10*