

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4	\$ 2.29
1	Curb	Cock Valve T. S. & V.	3/4 in.	\$ 2.70
	Service Box	Short	3 1/2 x 4 1/2	\$ 4.25
	Old returned	Long	4 1/2 x 5 1/2	
		Buff. or Rdway		
31	Ft.	3/4 in.	Pipe at	35 \$ 10.85
			Copper	
			Galv. Iron	
			Cast Iron	
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
2	Hrs. Foreman	at	WMM-1-1.12	\$ 2.24
3	Hrs. Chauffeur	at	WMM-2-1.02	\$ 3.06
	Hrs. Tapper	at		\$
7	Hrs. Labor	at	91	\$ 63.7
	Hrs. Labor	at		\$
1	Hrs. Compressor	at	1.20	\$ 1.20
	Compensation Ins.			\$ 2.6
	Trucking			\$ 1.-
	Builders Use of Water		B.P.	\$
	Tap w/ Miller			\$
				\$
				\$
				\$
				\$ 33.62

82-190

-St.
-Pl.
Ave. No. 46

Name of Owner

Lada E. Herrick

Labor and Mat'l. Report

June 23 1950



4 Main

Elev. of Main at tap 4 1/2

Gate at

Gate at

Curb Box

to be filled