

Labor and Materials

1	Copper } Connection.....	\$ 2.60
	Lead	
1	Curb } Cock Valve } in.....	\$ 2.27
	T.S. & V.	
1	Service Box } Short 3/4 x 1 1/2 }	\$ 1.38
	Old returned } Long 4 x 5 1/2 } Buff. or Rdway	
11	Ft.....in. } Copper Galv. Iron } Pipe at.....	\$ 1.98
	Cast Iron	
	Nipples.....in. at.....	\$
1	Bushings. 3/4 to 1/2 in. at.....	\$.10
	Red'g } Couplings.....to.....in. at.....	\$
	Inc'g }	
	Union.....in. at.....	\$
	Meter.....in. at.....	\$
	Lbs. Br. Stone at.....	\$
	Lbs. Sand at.....	\$
	Bags Cement 'at.....	\$
	Paving Brick } Mack Red } at.....	\$
	Asphalt	
	Lead Joints at.....	\$
	Leadite Joints at.....	\$
3/4	Hrs. Foreman at.....	\$ 47
3/4	Hrs. Common Labor at.....	\$ 38
6 1/2	Hrs. Common Labor at.....	\$ 2.93
	Hrs. Mason at.....	\$
	Hrs. Mason's Helper at.....	\$
	Hrs. Compressor at.....	\$
	Compensation Ins.....	\$.12
	Trucking.....	\$ 1.-
	Builders' Use of Water.....	\$
	Total \$	13.73

31-199

Labor and Material Report H-24 - 19

52 Harmon Ave



6 Main

Elev of Main at tap 5

Gate at ●

● Gate at

● Curb Box

Old tap dis

3.8 cu