

LABOR AND MATERIALS

1	Lead Copper	Connection	$\frac{3}{4}$ "		\$
1	Curb	Cock Valve T.S. & V.	$\frac{3}{4}$ in.		\$
1	Service box Old returned	Short $3\frac{1}{2}$ x $4\frac{1}{2}$ Long $4\frac{1}{2}$ x $5\frac{1}{2}$ Buff. or Rdway			\$
16	$\frac{3}{4}$ in.	Copper G.I. G.I.	Pipe at		\$
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	Coupl'gs. to in. at			\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints	at			\$
	Compound Joints	at			\$
	Maintenance Foreman				\$
	Hrs. Water Maint. Man-1	at			\$
	Hrs. Water Maint. Man-2	at			\$
	Hrs. Garage Foreman	at			\$
	Hrs. Labor	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.	at \$ per C			\$
	Trucking				\$
	Pav't Patch				\$
	Tap by <i>Gismond & Co</i>				\$
	<i>10-28-57</i>				\$
	O'head				\$
					\$

V
~~St.~~
~~Pl.~~
 Ave. No. 60

Harrison

Name of Owner A Jones

Labor and Mat'l. Report Oct. 28 1957

6" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

LSM-5C-2-5 56