

Labor and Materials

1	Copper } Connection.....	$\frac{3}{4}$	\$ 2.70
1	Lead } Cock Valve } T. S. & V. } in.....	$\frac{3}{4}$	\$ 2.39
1	Service Box } Short $3\frac{1}{2} \times 4\frac{1}{2}$ } Old returned } Long $4\frac{1}{2} \times 5\frac{1}{2}$ } Buff. or Rdway }		\$ 1.55
8	Ft.....in. } Copper } Galv. Iron } Cast Iron } Pipe at.....	$\frac{3}{4}$	\$ 2.16
	Nipples.....in. at.....		\$
	Bushings.....to.....in. at.....		\$
	Red'g } Inc'g } Couplings.....to.....in. at.....		\$
	Union.....in. at.....		\$
	Meter.....in. at.....		\$
	Lbs. Br. Stone at.....		\$
	Lbs. Sand at.....		\$
	Bags Cement 'at.....		\$
	Paving Brick } Mack } Red } Asphalt } at.....		\$
	Lead Joints at.....		\$
	Leadite Joints at.....		\$
4	Hrs. Foreman at.....		\$ 2.50
1.7	Hrs. Common Labor at.....		\$ 5.40
	Hrs. Common Labor at.....		\$
	Hrs. Mason at.....		\$
	Hrs. Mason's Helper at.....		\$
	Hrs. Compressor at.....		\$
	Compensation Ins.....		\$.24
	Trucking.....		\$ 1.00
	Builders' Use of Water.....	Patch	\$ 5.00
Total \$			22.94

7 Harrison Ave
Labor and Material Report *May 14* 19*30*

22' 5" 21' 8"

● Curb Box

4 Main Elev of Main at tap *5.2*

Gate at ● Gate at ●

TAX ID # 302.20-1-8

● Curb Box

old tape, Harrison