

LABOR AND MATERIALS

1	Copper	} Connection	3/4"	\$	
	Lead				
1	Curb	} Cock Valve	3/4 in.	\$	
		T.S. & V.			
1	Service box	} Short 3 1/2 x 4 1/2		\$	
	Old returned				Long 4 1/2 x 5 1/2
					Buff or Rdway
28	3/4 in.	} Copper	Pipe at	\$	
					G.I.
					G.I.
	Nipples	in. at	\$		
	Bushings	to in. at	\$		
	Red'g	} Coupl'gs	to in. at	\$	
	Inc'g				
	Union	in. at	\$		
	Meter	in. at	\$		
	Lead Joints	at	\$		
	Compound Joints	at	\$		
	Maintenance Foreman		\$		
	Hrs. Water Maint. Man-1	at	\$		
	Hrs. Water Maint. Man-2	at	\$		
	Hrs. Garage Foreman	at	\$		
	Hrs. Labor	at	\$		
	Hrs. Compressor	at	\$		
	Compensation Ins. at \$	per C.	\$		
	Trucking		\$		
	Pav't Patch		\$		
	Tap by Gifford & Co		\$		
	10-21-58		\$		
	O'head		\$		

St. Harrison Ave. No. 12  
 Pl. \_\_\_\_\_  
 Name of Owner C. Wilson Herchleb  
 Labor and Mat'l. Report Oct. 21 1958

4" Main Elev. of Main at tap 5'  
 Gate at ● Gate at ●  
 ● Curb Box  
 CURB BOX seems BACKWARDS

LSM-5C-2-5 56