

LABOR AND MATERIALS

None	Copper	Connection	\$	—
	Lead	Cock	\$	—
1	Curb	Valve	3/4" in.	\$	2.49
		T. S. & V.	\$	—
1	Service box	Short 3 1/2 X 4 1/2	\$	4.74
	Old returned	Long 4 1/2 X 5 1/2	\$	—
		Buff or Rdway	\$	—
16'8"	16'8" Ft.	Copper	\$	3.50
		G. I.	\$	—
		C. I.	\$	—
1	Nipples	1/2 in. at	Brass 3" L	\$	26
1	Bushings	3/4 to 1/2 in. at	\$	25
1	Red'g	3/4 to 1/2 in. at	Brass	\$	26
1	Inc'g	Coupl'gs	\$	—
1	Union	3/4 in. at	\$	1.53
	Meter	in. at	\$	—
	Lead Joints at	\$	—	
	Compound Joints at	\$	—	
	Hrs. Water Maint. Man—1 at	\$	—	
6	Hrs. Water Maint. Man—2 at	1.24	\$	7.44
12	Hrs. Labor— at	1.13	\$	13.56
	Hrs. Labor— at	\$	—	
	Hrs. Compressor at	\$	—	
	Compensation Ins. at	\$3.706 per C	\$	78
	Trucking	\$	1.02	
	Pav't Patch	\$	—	
	Tap by Gifford	\$	—	
	O'head	\$	—	
			\$	3.403	

St. Pl. Ave. No. 9

Harrison

Name of Owner Berkowitz

Labor and Mat'l. Report July 8 1953

14'-10" 28'-4"

● Curb Box

6" Main 1995 Elev. of Main at tap 4 1/2'

Gate at ● Gate at ●

● Curb Box

LSM-SC 5 15-48