

LABOR AND MATERIALS

Copper } Connection		\$	—
Lead } Clock Valve			
1 Curb } T.S. & V.	3/4 in.	\$	2.61
1 Service box } Short 3/4 X 4 1/2			
Old returned } Long 4 1/2 X 5 1/2		\$	1.82
9 Ft. } Copper	3/4 in.		
	Galv. Iron	Pipe at 23	\$ 2.07
	Cast Iron		
Nipples	in. at	\$	
1 B-shings	1" to 3/4 in. at	\$?
Red'g } Couplings	to in. at	\$	
Inc'g }			
Union	in. at	\$	
Meter	in. at	\$	
Lead Joints	at	\$	
Compound Joints	at	\$	
2 Hrs. Foreman	at WWM .24	\$	1.68
2 Hrs. Chauffeur	at 75	\$	6.00
Hrs. Tapper	at	\$	
8 Hrs. Labor	at 65	\$	5.20
Hrs. Labor	at	\$	
Hrs. Compressor	at	\$	
Compensation Ins.		\$	35
Trucking		\$	1.00
Builders Use of Water		\$	5.00
Used 3 one Tap 3/4"		\$	
Taply Warsawskis		\$	
		\$	
		\$	
		\$	25.73

+

✓

7-46

Sr
Pl
Ave. No. 33

Name of Owner
F Morse

Labor and Mat'l. Report *Mar 29* 19*46*

33

6 Main Elev. of Main at tap *4 1/2*

Gate at ● Gate at ●

● Curb Box