Labor and Materials

1	Lead Connection	$
1	Curb Cock	$
1	Service Box Old returned (Short 3½ x 4½ / ~~Long 4½ x 5½~~ / ~~Buffalo~~)	$
36	Ft. ¾ in. G. I. Pipe at Copper	$
	Nipples in. at	$
1	Bushings ¾ to ½ in. at	$
1	Red'g Coup ¾ to ½ in. at	$
	Inc'g Coup to in. at	$
	Union in. at	$
	Meter in. at	$
	Cu. Yds. Br. Stone at	$
	Cu. Yds. Sand at	$
	Bags Cement at	$
	Paving Brick (Mack / Red / Asphalt) at	$
	Hrs. Foreman at	$
3	Hrs. Common Labor at	$
	Hrs. Mason at	$
2	Hrs. Labor at	$
	Hrs. at	$
	Builders' Use of Water	$
	at	$
	at	$
	at	$
	at	$
	Total	$ 15.62

Labor and Material Report 1925

38 Lundell Ave. ✓

6 Main — Elev. of Main at tap 4

Gate at ● — ● Gate at

● Curb Box

Removed Found to Be Copper 10/30/25