

Labor and Materials

.....	Copper	Connection.....	3	\$ 96
.....	Curb	{ Cock Valve }	3	\$ 1.33
.....	Service Box	{ Short 3 1/2 x 4 1/2 }		\$ 1.35
.....	Old returned	{ Long 4 1/2 x 6 1/2 }		
.....	2 1/2 Ft. 3/4 in.	{ Copper Galv. Iron Cast Iron } Pipe at 1.54		\$ 3.90
.....	Nipples in. at		\$
.....	Bushings to in. at		\$
.....	Red'g Inc'g	{ Couplings..... to in. at		\$
.....	Union in. at		\$
.....	Meter in. at		\$
.....	Lbs. Br. Stone	at		\$
.....	Lbs. Sand	at		\$
.....	Bags Cement	at		\$
.....	Paving Brick	{ Mack Red Asphalt } at		\$
.....	Lead Joints	at		\$
.....	Leadite Joints	at		\$
.....	7 Hrs. Foreman	at 62 1/2		\$ 4.38
.....	4 Hrs. Common Labor	at 50		\$ 2.00
.....	28 Hrs. Common Labor	at 45		\$ 12.60
.....	Hrs. Mason	at		\$
.....	Hrs. Masons Helper	at		\$
.....	Hrs. Compressor	at		\$
.....	Compensation Ins		\$ 58
.....	Trucking		\$ 1.00
.....	Builders Use of Water	no patch		\$
				Total \$ 28.10

2-36

Labor and Material Report *May* 2 1938

44 *Haskell Ave*

1968

25' 7"

24-4

24-4

● Curb Box

6 Main Elev. of Main at tap 4

Gate at ● ● Gate at

● Curb Box

old sheet off of main

MB