

Labor and Materials

1	Copper } Connection.....	3/4	\$ 1.33
1	Lead } Cock Valve } in.....	3/4	\$ 1.58
1	Service Box } Short 3 1/2 x 4 1/2 } Old returned } Long 4 1/2 x 5 1/2 } Buff. or Rdway }		\$ 1.36
28	Ft. in. } Copper } Galv. Iron } Cast Iron }		\$ 2.66
	Nipples ..... in. at .....		\$ .....
	Bushings ..... to ..... in. at .....		\$ .....
	Red'g } Couplings..... to..... in. at.....		\$ .....
	Inc'g }		\$ .....
	Union..... in. at .....		\$ .....
	Meter..... in. at .....		\$ .....
	Lbs. Br. Stone at .....		\$ .....
	Lbs. Sand at .....		\$ .....
	Bags Cement at .....		\$ .....
	Paving Brick } Mack } Red } Asphalt }		\$ .....
	Lead Joints at .....		\$ .....
	Leadite Joints at .....		\$ .....
14	Hrs. Foreman at .....		\$ 2.75
	Hrs. Common Labor at .....		\$ .....
18	Hrs. Common Labor at .....		\$ 8.10
	Hrs. Mason at .....		\$ .....
	Hrs. Masons Helper at .....		\$ .....
	Hrs. Compressor at .....		\$ .....
	Compensation Ins .....		\$ .52
	Trucking .....		\$ 1.-
	Builders Use of Water Patch .....		\$ 5.-
Total \$			30.30

33-44

Labor and Material Report July 11 19

46 Haskell Ave



Main Elev. of Main at tap 5

Gate at TAX ID # 303.18-3-22 Gate at

Curb Box

old Tap shut off at main

Q/M

CM