

**Labor and Materials**

Copper } Connection.....	?	\$ 3.20
Lead } .....	4	
Curb } Cock } .....	3 in.	\$ 1.00
} Valve } .....		
} T. S. & V. } .....		
Service Box } Short 3 1/2 x 4 1/2 } .....		\$ 1.30
Old returned } Long 3 x 4 } .....		
} Butt or Redway } .....		
2 1/2 Ft. } 3 in. } Copper } Pipe at.....		\$ 5.72
} Galv. Iron } .....		
} Cast Iron } .....		
Nipples..... in. at.....		\$
Bushings..... to..... in. at.....		\$
Red'g } Couplings..... to..... in. at.....		\$
Inc'g } .....		
Union..... in. at.....		\$
Meter..... in. at.....		\$
Lbs Br. Stone at.....		\$
Lbs. Sand at.....		\$
Bags Cement at.....		\$
Paving Brick } Mack } at.....		\$
} Red } .....		
} Asphalt } .....		
Lead Joints at.....		\$
Leadite Joints at.....		\$
3 Hrs. Foreman at.....		\$ 1.87
Hrs. Common Labor at.....		\$
16 Hrs. Common Labor at.....		\$ 6.50
Hrs. Mason at.....		\$
Hrs. Mason's Helper at.....		\$
Hrs. Compressor at.....		\$
Compensation Ins.....		\$ 22
1 Trucking.....		\$ 1.00
Builders' Use of Water.....		\$
<b>Total</b>		<b>\$ 20.81</b>

27-122

**Labor and Material Report**

July 26 19 27

58 Haskell Ave



6 Main

Elev. of Main at tap 4 1/2

Gate at ●

● Gate at

● Curb Box

old 15 Be dug up