

Labor and Materials

1	Copper } Connection	3/4		\$ 3.20
1	Curb } Cock			
		3/4 in.		\$ 1.00
		P.S. & V.		
1	Service Box } Short 3 1/2 x 4 1/2			\$ 1.30
	Old returned } Long 4 1/2 x 5 1/2			
		Buff. or Rdway		
10	Ft. } 3/4 in. } Copper		2 v	\$ 2.20
		Galv. Iron		
		Cast Iron		
1	Nipples	in. at		\$
1	Bushings	3/4 in. to 1/2 in. at		\$.88
	Red'g } Couplings	to in. at		\$
	Inc'g }			
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone at			\$
	Lbs. Sand at			\$
	Bags Cement at			\$
	Paving Brick } Mack			\$
		Red		
		Asphalt		
	Lead Joints at			\$
	Leadite Joints at			\$
3	Hrs. Foreman at	6 2/5		\$ 1.88
7	Hrs. Common Labor at	7 1/2		\$
20	Hrs. Common Labor at	40 1/2		\$ 8.12
	Hrs. Mason at			\$
	Hrs. Mason's Helper at			\$
	Hrs. Compressor at			\$
	Compensation Ins.			\$ 2.6
	Trucking			\$ 1.00
	Builders' Use of Water			\$
Total				\$ 19.04

Labor and Material Report *May 27* 19*26*

59. Holbrook Av.



6" Main

Elev. of Main at tap *5'*

Gate at ●

● Gate at

● Curb Box