

LABOR AND MATERIALS

1 Copper } Connection  $\frac{3}{4}$  in. \$ \_\_\_\_\_  
 1 Lead } Cock }  
 1 Curb } Valve }  $\frac{3}{4}$  in. \$ \_\_\_\_\_  
 } T. S. & V. }  
 1 Service box { Short  $3\frac{1}{2} \times 4\frac{1}{2}$  }  
 Old returned { Long  $4\frac{1}{2} \times 5\frac{1}{2}$  } \$ \_\_\_\_\_  
 } Buff or Rdway }  
 38  $\frac{3}{4}$  in. { Copper } Pipe at \$ \_\_\_\_\_  
 } G.I. }  
 } G.I. }  
 Nipples in. at \$ \_\_\_\_\_  
 Bushings to in. at \$ \_\_\_\_\_  
 Red'g }  
 Inc'g } Coupl'gs to in. at \$ \_\_\_\_\_  
 Union in. at \$ \_\_\_\_\_  
 Meter in. at \$ \_\_\_\_\_  
 Lead Joints at \$ \_\_\_\_\_  
 Compound Joints at \$ \_\_\_\_\_  
 Maintenance Foreman \$ \_\_\_\_\_  
 Hrs. Water Maint. Man-1 at \$ \_\_\_\_\_  
 Hrs. Water Maint. Man-2 at \$ \_\_\_\_\_  
 Hrs. Garage Foreman at \$ \_\_\_\_\_  
 Hrs. Labor at \$ \_\_\_\_\_  
 Hrs. Compressor at \$ \_\_\_\_\_  
 Compensation Ins. at \$ per C \$ \_\_\_\_\_  
 Trucking \$ \_\_\_\_\_  
 Pav't Patch \$ \_\_\_\_\_  
 Tap by Gifford & Co. 11-15-62 \$ \_\_\_\_\_  
 O'head \$ \_\_\_\_\_  
 \$ \_\_\_\_\_

Haskell St. \_\_\_\_\_  
 Ave. No. 70 Pl. \_\_\_\_\_

Name of Owner  
Robert O'Connor

Labor and Mat'l. Report Nov. 15 1962

