

LABOR AND MATERIALS

| | | | | | | |
|----|-------------------------|---------------------------------------|---------------------|---------|----|--|
| 1 | Copper Lead | Connection | $\frac{3}{4}$ " | | \$ | |
| 1 | Curb | Cock Valve | $\frac{3}{4}$ " in. | | \$ | |
| | | T.S. & V. | | | | |
| 1 | Service box | Short $3\frac{1}{2}$ x $4\frac{1}{2}$ | | | | |
| | Old returned | Long $4\frac{1}{2}$ x $5\frac{1}{2}$ | | | | |
| | | Buff or Rdway | | | \$ | |
| 25 | Ft. | Copper | | Pipe at | \$ | |
| | | G.I. | | | | |
| | | G.I. | | | | |
| | Nipples | in. at | | | \$ | |
| | Bushings | to in. at | | | \$ | |
| | Red'g Inc'g | Coupl'gs to in. at | | | \$ | |
| | Union | in. at | | | \$ | |
| | Meter | in. at | | | \$ | |
| | Lead Joints | at | | | \$ | |
| | Compound Joints | at | | | \$ | |
| | Maintenance Foreman | | | | \$ | |
| | Hrs. Water Maint. Man-1 | at | | | \$ | |
| | Hrs. Water Maint. Man-2 | at | | | \$ | |
| | Hrs. Garage Foreman | at | | | \$ | |
| | Hrs. Labor | at | | | \$ | |
| | Hrs. Compressor | at | | | \$ | |
| | Compensation Ins. | at \$ per C. | | | \$ | |
| | Trucking | | | | \$ | |
| | Pav't Patch | | | | \$ | |
| | Tap by Giggard + | | | | \$ | |
| | Co. 7-28-60. | | | | \$ | |
| | O'head | | | | \$ | |

Str. _____
 Pl. _____
 Ave. No. 76

Haskell

Name of Owner Robert O'Connor

Labor and Mat'l. Report July 28 1960.

6" Main

Gate at ●

Elev. of Main at tap 6'1/2"

● Gate at

● Curb Box

LSM-5C-2-5 56