

Labor and Materials

1	Copper } Connection	3	\$ 2.60
	Lead } "	1	
1	Curb } Cock	3	\$ 2.30
	Valve } in.		
	T. S. & V. }	4	
1	Service Box } Short 3/4x1 1/2		\$ 1.40
	Old returned } Long 1 1/2x2 1/2		
			Buff. or Redway }
8	Ft. in. } Copper	3/4	\$ 2.12
			Galv. Iron } Pipe at
			Cast Iron }
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g } Couplings	to in. at	\$
	Inc'g }		
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick } Mack	at	\$
			Red }
			Asphalt }
	Lead Joints	at	\$
	Leadite Joints	at	\$
3	Hrs. Foreman	at	\$ 1.85
12	Hrs. Common Labor	at	\$ 4.85
	Hrs. Common Labor	at	\$
	Hrs. Mason	at	\$
	Hrs. Mason's Helper	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.		\$.18
	Trucking		\$ 1.00
	Builders' Use of Water	Patch	\$ 5.00
Total			\$ 21.36

Labor and Material Report

Aug 27 1922

15 Haswell Ave



33' 2"
Try 38'

27' 2"
Try 27' 8"

● Curb Box

Main Elev of Main at tap 4

Gate at ● ● Gate at

● Curb Box

TAX ID # 303.18-15-7

all leads connection

