LABOR AND MATERIALS

1	Copper / ~~Lead~~ Connection 3/4	$ 1.23
1	Curb { Cock / ~~Valve~~ / ~~T. S. & V.~~ } 3/4 in.	$ 1.68
1	Service Box ~~Old returned~~ { Short 3½x4½ / ~~Long 4½x5½~~ / ~~Buff. or Rdway~~ }	$ 1.54
10 Ft. 3/4 in.	{ Copper / ~~Galv Iron~~ / ~~Cast Iron~~ } Pipe at 17	$ 1.70
	Nipples ____ in. at	$
	Bushings ____ to ____ in. at	$
	Red'g / Inc'g Couplings ____ to ____ in. at	$
	Union ____ in. at	$
	Meter ____ in. at	$
	Lead Joints at	$
	Leadite Joints at	$
	Hrs. Foreman at	$
3	Hrs. Chauffeur at 62½	$ 1.87
1	Hrs. Tapper at	$ .63
4	Hrs. Labor at 45	$ 1.80
	Hrs. Labor at	$
	Hrs. Compressor at	$
	Compensation Ins.	$ .14
	Trucking	$ 1.—
	Builders Use of Water Patch	$ 5.—
Taylor Hessel		$
		$
		$
		$
		$ 16.59

3 9 — 1939

~~St.~~ ~~Pl.~~ Haviland Ave. No. 29

Name of Owner

~~Potter~~ Doyle

Labor and Mat'l. Report July 1 1939

4" Main

Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

old Shutoff