

LABOR AND MATERIALS

Copper	}	Connection	\$	
Lead				
Curb	}	Cock	in.	\$
		Valve		
		T. S. & V.		
Service box	}	Short 3½ x 4½	\$	
Old returned		Long 4½ x 5½		
		Buff or Rdway		
P Ft. 3/4 in.	}	Copper	\$	
Nipples	in. at		\$	
Bushings	to in. at		\$	
Red'g Inc'g	}	Coupl'gs	to in. at	\$
Union		in. at		
Meter	in. at		\$	
Lead Joints	at		\$	
Compound Joints	at		\$	
Maintenance Foreman			\$	
Hrs. Water Maint. Man	—1 at		\$	
Hrs. Water Maint. Man	—2 at		\$	
Hrs. Garage Foreman	at		\$	
Hrs. Labor	at		\$	
Hrs. Compressor	at		\$	
Compensation Ins.	at \$ per C		\$	
Trucking			\$	
Pav't Patch			\$	
			\$	
			\$	
O'head			\$	
			\$	

St. Pl. Ave. No. 5

HAVILAND

Name of Owner T. McDonnell

MEASURED IN JUNE 11 1972

Labor and Mat'l. Report

● Curb Box

TAP ON KNIGHT ST

Main Elev. of Main at tap

Gate at ● ● Gate at

● Curb Box

LSM-5C-6-1-67

Labor and Materials

1	Copper } Connection	$\frac{3}{4}$	\$ 320
1	Curb } Cock } Valve } P.S. } W.	in $\frac{3}{4}$	\$ 100
1	Service Box } Short $3\frac{1}{2} \times 4\frac{1}{2}$ } Old returned } (Long 4") Rail or R.daway }		\$ 130
2	Ft. in. } Copper } Galv. Iron } Cast Iron }	Pipe at $\frac{3}{4}$	\$ 176
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g } Inc'g }	Couplings to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick } Mack } Red } Asphalt }	at	\$
	Lead Joints	at	\$
	Leadite Joints	at	\$
	Hrs. Foreman	at	\$
2	Hrs. Common Labor	at 6.25	\$ 125
6	Hrs. Common Labor	at 5.00	\$ 300
6	Hrs. Mason	at $40\frac{1}{2}$	\$ 244
	Hrs. Mason's Helper	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.		\$ 18
	Trucking		\$ 100
	Builders' Use of Water		\$
	Total		\$ 1513

27-156

5

Labor and Material Report

Sept 19 1927

Remounting cur



Main

Elev. of Main at tap 5

Gate at

Gate at

Curb Box

old tap disconnected