

LABOR AND MATERIALS

1	Copper Lead	{ Connection	3/4	\$ 1.23	
1	Curb	{ Cock Valve T. S. & V.	3/4 in.	\$ 1.68	
1	Service Box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway		\$ 1.54	
8	Ft. 3/4 in.	{ Copper Galv Iron Cast Iron	Pipe at 17	\$ 1.36	
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	{ Couplings to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
	Hrs. Foreman	at		\$	
2	Hrs. Chauffeur	at	6 1/2	\$ 1.25	
4	Hrs. Tapper	at		\$ 2.50	
4	Hrs. Labor	at	45	\$ 1.80	
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins.			\$.17	
	Trucking			\$ 1.00	
	Builders Use of Water	Patch		\$ 5.00	
	Tap by Hessel			\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$ 17.53	

76 - - 1939

St. 33

-Pl. 35

Haviland Ave. No. 35

Name of Owner

Cronnell

Labor and Mat'l. Report

Sept 15 1939



7 Main

Elev. of Main at tap 5

Gate at ●

● Gate at

● Curb Box

old shot off