

LABOR AND MATERIALS

1	Copper	Lead	Connection	3/4	\$	2.87
1	Curb	Cock Valve	T. S. & V.	3/4	\$	3.62
	Service box	Old returned	Short 3/4 X 4 1/2 Long 4 1/2 X 5 1/2 Buff or Rdway		\$	4.68
29	Ft.	3/4	in.	Copper G. I. C. I.	Pipe at 32	\$	7.68
.....	Nipples	in.	at	\$	
.....	Bushings	to	in.	at
.....	Red'g Inc'g	Coupl'gs	to	in.	at
.....	Union	in.	at	\$	
.....	Meter	in.	at	\$	
.....	Lead Joints	at	\$	
.....	Compound Joints	at	\$	
.....	Hrs. Water Maint. Man	-1	at	\$	
6	Hrs. Water Maint. Man	-2	at	1.02	\$	6.12
22	Hrs. Labor	-	at	91	\$	20.02
.....	Hrs. Labor	-	at	\$	
.....	Hrs. Compressor	at	\$	
.....	Compensation Ins.	at \$2.18	per C	\$	57
.....	Trucking	\$	2.00
.....	Pav't Patch	\$	10.25
.....	Tap by M. J. W.	\$	
.....	O'head	\$	
						\$	57.81

60

St. 12
Pl. 24
Ave. No. 24

Name of Owner
Howard

Name of Owner
Clendenen W. Co. Inc.

Labor and Mat'l. Report *June 21* 19 *49*

Main Elev. of Main at tap

Gate at ● Gate at ●

● Curb Box

LBM-5C 5 15-48