

Labor and Materials

1	Copper } Connection	3/4	\$ 2.60
	Lead		
1	Curb } Cock	3/4 in.	\$ 2.30
	Valve		
	T-S. & V.		
1	Service Box } Short 3 1/2 x 4 1/2		\$ 1.40
	Old returned } Long 4 1/2 x 5 1/2		
		Buff. or Rdway	
7	Ft. } in.	3/4	\$ 1.86
		Copper	
		Galv. Iron	
		Cast Iron	
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g } Couplings	to in. at	\$
	Inc'g		
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick } Mack	at	\$
		Red	
		Asphalt	
	Lead Joints	at	\$
	Leadite Joints	at	\$
6	Hrs. Foreman	at	\$ 3.75
	Hrs. Common Labor	at	\$
	Hrs. Common Labor	at	\$
	Hrs. Mason	at	\$
	Hrs. Mason's Helper	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.		\$ 1.00
	Trucking		\$ 1.00
	Builders' Use of Water		\$
			Total \$ 13.01

29-192

Labor and Material Report

19

Oct. 31
12 Henry St.



6" Main

Elev of Main at tap 4.12

Gate at ●

● Gate at

● Curb Box

Old tap shut off

TAX ID # 309.12-5-6