

LABOR AND MATERIALS

1	Copper	Connection	3/4"		\$ 1.23
1	Curb	Cock Valve T. S. & V.	3/4" in.		\$ 1.68
1	Service Box	Old returned {	Short 3 1/2 x 4 1/2	}	\$ 1.75
			Long 4 1/2 x 5 1/2		
9	Ft.	3/4 in.		Pipe at 1/5	\$ 1.35
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	Couplings to in. at			\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints	at			\$
	Leadite Joints	at			\$
	Hrs. Foreman	at			\$
7	Hrs. Chauffeur	at	6 2/2		\$ 4.37
2	Hrs. Tapper	at	"		\$ 1.25
	Hrs. Labor	at			\$
4	Hrs. Labor	at	45		\$ 1.80
	Hrs. Compressor	at			\$
	Compensation Ins.				\$.23
	Trucking				\$ 1.50
	Builders Use of Water		Batch		\$ 2.50
					\$
					\$
					\$
					\$
					\$
					\$
					\$ 17.16

140 - 1938

St.
Pl.
Ave. No.

4 Henry

Name of Owner

Labor and Mat'l. Report Oct. 14 19 38



" Main

Elev. of Main at tap 5 1/2'

Gate at ● ● Gate at

● Curb Box

Old house never had H₂O before

TH