

LABOR AND MATERIALS

1	Copper	Connection	$\frac{3}{4}$ "	\$
1	Lead			\$
1	Curb	Cock Valve T.S. & V.	$\frac{3}{4}$ in.	\$
1	Service box	Short $3\frac{1}{2} \times 4\frac{1}{2}$		\$
	Old returned	Long $4\frac{1}{2} \times 5\frac{1}{2}$		\$
		Buff or Rdway		\$
7	Ft. $\frac{3}{4}$ in.	Copper Pipe at		\$
		G.I.		\$
		G.I.		\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g			\$
	Inc'g	Coupl'gs to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.	at \$ per C		\$
	Trucking			\$
	Pav't Patch			\$
	Tap by Hessel			\$
		8-26-37		\$
	O'head			\$

St. Pl. Ave. No. 4

Holman

Name of Owner Rose

Labor and Mat'l. Report Aug 26 19 37

#4

17'7"      13'6"

● Curb Box

4" Galv. Main      Elev. of Main at tap 5'

Gate at ●      ● Gate at

● Curb Box  
FACING HOUSE LEFT TOP  
EDGE BEGINING OF DRIVEWAY  
" KH  
5-23-2001

L M-5C-2-1-54