

# LABOR AND MATERIALS

Copper	} Connection	-----	\$	
Lead				
Curb	} Cock Valve T. S. & V.	-----	in. ----- \$	
Service Box				
Old returned	} Short 3/2x4 1/2 Long 4 1/2x5 1/2 Buff. or Rdway	-----	\$	
		} Copper Galv Iron Cast Iron	-----	Pipe at ----- \$
Ft. -----			in. -----	
Nipples	in. at -----		\$	
Bushings	to ----- in. at -----		\$	
Red'g Inc'g	} Couplings	to ----- in. at -----	\$	
Union	in. at -----		\$	
Meter	in. at -----		\$	
Lead Joints	at -----		\$	
Leadite Joints	at -----		\$	
Hrs. Foreman	at -----		\$	
Hrs. Chauffeur	at -----		\$	
Hrs. Tapper	at -----		\$	
Hrs. Labor	at -----		\$	
Hrs. Labor	at -----		\$	
Hrs. Compressor	at -----		\$	
Compensation Ins.	-----		\$	
Trucking	-----		\$	
Builders Use of Water	-----		\$	
			\$	
			\$	
			\$	
			\$	

St. \_\_\_\_\_  
 Pt. \_\_\_\_\_  
 Ave. No. 11

Holman

Name of Owner \_\_\_\_\_

---

Labor and Mat'l. Report 19 14

Main Elev. of Main at tap -----

Gate at ● ● Gate at

---

7-9

11

37' 4"

37' 6"

Curb Box

Gate at

Gate at

Main at tap

Main

GLOBE VALVE

Curb Box

27' 7"

5' 0"

11

7-9

19 14

Labor and Mat'l. Report

Name of Owner

Holman

St.

Ave. No.

11