

LABOR AND MATERIALS

1	Copper Lead	} Connection	3/4"		\$
1	Curb	{ Cock Valve 7.6.2.V. }	3/4"	in.	\$
	Service Box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buffer Rdway }			\$
8	Ft.	in.	{ Copper Galv Iron Cast Iron }	Pipe at	\$
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	} Couplings	to in. at		\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints at				\$
	Leadite Joints at				\$
	Hrs. Foreman at				\$
	Hrs. Chauffeur at				\$
	Hrs. Tapper at				\$
	Hrs. Labor at				\$
	Hrs. Labor at				\$
	Hrs. Compressor at				\$
	Compensation Ins.				\$
	Trucking				\$
	Builders Use of Water				\$
	Tap made 6-23-1930				\$
					\$
					\$
					\$
					\$

St. _____
 Pl. _____
 Ave. No. 19

Horicon

Name of Owner _____

June 23, 1930

Labor and Mat'l. Report AUG 22 1930 19

Main

Elev. of
Main at tap

Gate at ●

● Gate at

● Curb Box

59' 7" 57' 8"