

Labor and Materials

1	Lead Connection 1"	\$	
1	Curb Cock 1/4" Dia	\$	
1	Service Box { Short 3 1/2 x 4 1/2 Old returned Long 4 1/2 x 5 1/2 Buffalo	\$	
8	1/4" in. G. I. Pipe at	\$	
	Nipples.....in. at	\$	
	Bushings.....in. at	\$	
	Red'g Coup...to...in. at	\$	
	Inc'g Coup...to...in. at	\$	
	Union...in. at	\$	
	Meter...in. at	\$	
	Cu. Yds. Br. Stone at	\$	
	Cu. Yds. Sand at	\$	
	Bags Cement at	\$	
	Pav. Brick { Mack Red Asphalt } at	\$	
2 1/2	Hrs. Foreman at	\$	
7	Hrs. Com. Labor at	\$	
	Hrs. Mason at	\$	
	Hrs.at	\$	
	Hrs.at	\$	
9.5	Builders' Use of Water	\$	
	at	\$	
	Tracks 100	\$	
	at	\$	
	at	\$	
	Old Connection Shut off at main	\$	
	Total	\$	14.20

Labor and Material Report

1923

1" Tap at 15 Harrison Ave



Curb Box

6" Main

Elev. of Main at tap 5 1/2

Gate at ●

● Gate at

TAX ID # 302.15-1-14

● Curb Box

Drawn in Book July 11 1923 J.P.S.