

Labor and Materials

1	Lead Connection	1/2	\$
1	Curb Cock	3/8	\$
1	Service Box	(Short 3 1/2 x 4 1/2)	\$
	Old returned	(Long 4 1/2 x 5 1/2)	\$
		(Buffalo)	\$
8	Ft. 3/4 in. G. I. Pipe	at	\$
	Nipples in. at	\$
	Bushings in. at	\$
	Red'g Coup	... to ... in. at	\$
	Inc'g Coup	... to ... in. at	\$
	Union in. at	\$
	Meter in. at	\$
	Cu. Yds. Br. Stone	at	\$
	Cu. Yds. Sand	at	\$
	Bags Cement	at	\$
	Pav. Brick	{ Mack } at	\$
		{ Red }	\$
		{ Asphalt }	\$
3	Hrs. Foreman	at	\$
14	Hrs. Com. Labor	at	\$
	Hrs. Mason	at	\$
	Hrs. at	\$
	Hrs. at	\$
yes	Builders' Use of Water	\$
	Tracks at	\$
	 at	\$
	 at	\$
	 at	\$
	Total		\$ 13.36	

Labor and Material Report

Jan 15-16 1922

1/2 Tap at 21 Horicon Ave

