

LABOR AND MATERIALS

1	Copper	Connection	3/4"	\$
1	Curb	Cock Valve	3/4 in.	\$
		T. S. & V.		
1	Service box	Short 3 1/2 x 4 1/2		
	Old returned	Long 4 1/2 x 5 1/2		
		Buff or Rdway		\$
31	Ft.	3/4 in. Copper	Pipe at	\$
		G.I.		
		G.I.		
	Nipples	in. at		\$
	Bushings	to in. at		\$
1	Red'g Inc'g	Coupl'gs. 3/4" to	CO.P. TO COP.	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins. at \$	per C		\$
	Trucking			\$
	Pay't Patch			\$
	Tap by Gifford & Co.			\$
	2-5-59			\$
	Started Jan 29 - Feb. 6			\$
	O'head			\$
				\$

✓

Horicon St. Pl. Ave. No. 26

---

Name of Owner  
Dr. Jos. Pertus

---

Labor and Mat'l. Report 19

garage Door 75' 8" 48' 6" ● Curb Box

---

6" Main Elev. of Main at tap 5 1/2'

---

Gate at ● ● Gate at

---

TAX ID # 302.15-6-5

---

● Curb Box

LSM-5C-2-5 56