

LABOR AND MATERIALS

Copper	}	Connection	\$	
Lead			\$	
Curb	{	Cock Valve T. S. & V.	in. \$	
Service Box			}	\$
Old returned				
Ft.	{	Pipe at	\$	
in.			Copper	\$
			Galv Iron Cast Iron	\$
Nipples	in. at	\$		
Bushings	to in. at	\$		
Red'g Inc'g	}	Couplings to in. at	\$	
Union			in. at	\$
Meter	in. at	\$		
Lead Joints	at	\$		
Leadite Joints	at	\$		
Hrs. Foreman	at	\$		
Hrs. Chauffeur	at	\$		
Hrs. Tapper	at	\$		
Hrs. Labor	at	\$		
Hrs. Labor	at	\$		
Hrs. Compressor	at	\$		
Compensation Ins.		\$		
Trucking		\$		
Builders Use of Water		\$		
		\$		
		\$		
		\$		
		\$		
		\$		

St:
 Pt:

Harison

Ave. No. *39*

Name of Owner
Mead

Tied in

Labor and Mat'l Report *Oct. 31* 19*38*

6" Main Elev. of Main at tap

Gate at ● ● Gate at

● Curb Box

Labor and Materials

Copper } Connection.....	3		\$ 2.60
Lead } Curb { Cock	73	in.	\$ 2.30
Valve } T. S. & V. }			
Service Box } Short 3/4x1/2	}		\$ 1.50
Old returned } Long 4/4x5/4 Buff. or Rdway }			
14 Ft. in. } Copper	3	in. at	\$ 2.65
Galv. Iron } Cast Iron }			
Nipples.....		in. at	\$
Bushings.....		to in. at	\$
Red'g } Couplings.....		to in. at	\$
Inc'g }			
Union.....		in. at	\$
Meter.....		in. at	\$
Lbs. Br. Stone at.....			\$
Lbs. Sand at.....			\$
Bags Cement 'at.....			\$
Paving Brick } Mack } at.....			\$
Red }			
Asphalt }			
Lead Joints at.....			\$
Leadite Joints at.....			\$
3 Hrs. Foreman at.....			\$ 1.88
8 Hrs. Common Labor at.....			\$ 3.25
Hrs. Common Labor at.....			\$
Hrs. Mason at.....			\$
Hrs. Mason's Helper at.....			\$
Hrs. Compressor at.....			\$
Compensation Ins.....			\$.14
Trucking.....			\$ 1.00
Builders' Use of Water.....	Patch		\$ 5.00
Total \$			19.32

Labor and Material Report

May 21 1929

39 Horicon Ave



● Curb Box

6 Main

Elev of Main at tap 5

Gate at ●

● Gate at

● Curb Box

Murray